

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL

P1TJ-QJAP-426



Solid Waste - Class 2 Landfill	
Facility	
Facility Name	PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL
Date of Inspection	5/26/2026
Time of Inspection	12:39 PM
County	Beaufort
Permit #	072410-1201
Inspection Processing	
Reason for Inspection	Routine
Weather Conditions	Partly Sunny
Temperature	80s
Rainfall in past week	0-0.5
Weather Condition Description	Extreme drought conditions. Wind 13mph, gusts up to 20mph.
Last Inspection	04/20/2026
Inspection Detail	
1. Attendant Present	Yes
2. Required signs posted	Yes
3. Inspection of all incoming loads conducted	Yes
4. Unauthorized waste training conducted and documented	Not Inspected
5. No unauthorized waste present	Yes
6. Access controlled	Yes
7. Adequate entrance all-weather roads	Yes
8. Adequate internal all-weather haul roads	Yes

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL

P1TJ-QJAP-426



Inspection Detail	
9. Frequency of cover meets regulatory/ permit requirements <i>Comments:</i> Cover being applied at time of inspection.	Yes
10. > Six inches of soil (short-term cover) meets regulatory/permit requirements	Yes
11. Approved Alternate Monthly Cover (AMC) used	Not Applicable
12. > Six inches of soil (long-term and/or intermediate cover) meets regulatory/permit requirements	Yes
13. Adequate soil quantity available for cover	Yes
14. Working face slope does not exceed 3:1	Yes
15. Waste spread in uniform layers and compacted to smallest practical volume	Yes

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL

P1TJ-QJAP-426



Inspection Detail

16. Working face as small as can efficiently and safely be managed Yes

Comments:

Working face a little large, cover being applied during inspection. Make sure this is a manageable size.

	<p>Photo Taken: 5/26/2026 12:51:00 PM GPS Latitude: 32.474763 GPS Longitude: -80.649222 GPS Altitude: 6.750000 meters GPS Orientation: 1 degrees</p>
--	--

	<p>Photo Taken: 5/26/2026 12:51:00 PM GPS Latitude: 32.474763 GPS Longitude: -80.649222 GPS Altitude: 6.750000 meters GPS Orientation: 1 degrees</p>
--	--

17. Asbestos containing material adequately handled Not Applicable

18. Dead animals adequately handled Not Applicable

19. All required equipment operational Yes

Comments:

Magnet back online.

20. Access to fire equipment and fire fighting services Yes

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL

P1TJ-QJAP-426



Inspection Detail

21. Disposal area graded to a minimum 1% slope	Yes
22. Adequate condition of ditches/swales	Yes
23. Adequate condition of berms/terraces/downchutes	Yes

Comments:

Eastern slope grass has moderate growth, still some bare spots.



Photo Taken: 5/26/2026 12:53:00 PM
GPS Latitude: 32.470997
GPS Longitude: -80.648925
GPS Altitude: 13.610000 meters
GPS Orientation: 1 degrees



Photo Taken: 5/26/2026 12:53:00 PM
GPS Latitude: 32.470919
GPS Longitude: -80.648688
GPS Altitude: 30.880000 meters
GPS Orientation: 1 degrees

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL

P1TJ-QJAP-426



Inspection Detail



May 26, 2026 at 12:53:15 PM
Beaufort, SC 29907
United States
Lady's Island

Photo Taken: 5/26/2026 12:53:00 PM
GPS Latitude: 32.470919
GPS Longitude: -80.648688
GPS Altitude: 30.880000 meters
GPS Orientation: 1 degrees

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL

P1TJ-QJAP-426



Inspection Detail

24. Adequate condition of sedimentation ponds

Yes



Photo Taken: 5/26/2026 1:09:00 PM
GPS Latitude: 32.467761
GPS Longitude: -80.648452
GPS Altitude: 10.270000 meters
GPS Orientation: 1 degrees



Photo Taken: 5/26/2026 1:09:00 PM
GPS Latitude: 32.467761
GPS Longitude: -80.648452
GPS Altitude: 10.270000 meters
GPS Orientation: 1 degrees

25. Control of Dust

Yes

Comments:

Hydroseeder truck being used currently to wet entrance area.

26. Control of Litter

Yes

Comments:

Litter in eastern ditches has been cleaned up. Litter fencing present on top near working face.

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL

P1TJ-QJAP-426



Inspection Detail



Photo Taken: 5/26/2026 12:56:00 PM
GPS Latitude: 32.471322
GPS Longitude: -80.648925
GPS Altitude: 27.320000 meters
GPS Orientation: 1 degrees



Photo Taken: 5/26/2026 1:05:00 PM
GPS Latitude: 32.471136
GPS Longitude: -80.647772
GPS Altitude: 7.780000 meters
GPS Orientation: 1 degrees




Photo Taken: 5/26/2026 1:05:00 PM
GPS Latitude: 32.471136
GPS Longitude: -80.647772
GPS Altitude: 7.780000 meters
GPS Orientation: 1 degrees

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL

P1TJ-QJAP-426



Inspection Detail	
27. Control of Odors	No
<i>Comments:</i> H2S odor detectable along Middle Rd prior to arriving at site for inspection.	
28. Control of Vectors	Yes
29. Control of Fires/Open Burning	Yes
30. Scales installed and functioning properly	Yes
31. Scales calibrated adequately	Yes
<i>Comments:</i> Inspected for accuracy by SC Dept of Agriculture, sticker located.	
<div style="display: flex; align-items: flex-start;">  <div style="margin-left: 20px;"> <p>Photo Taken: 5/26/2026 12:42:00 PM GPS Latitude: 32.474705 GPS Longitude: -80.649186 GPS Altitude: 6.750000 meters GPS Orientation: 6 degrees</p> </div> </div>	
31a. Last date of calibration	5/18/2026
32. Monitoring well pads are free of sediment buildup and standing water	Not Inspected
33. Monitoring wells pads are free of cracks	Not Inspected
34. Monitoring wells are labeled	Not Inspected
35. Monitoring wells are locked	Not Inspected
36. Operating in accordance with approved plans	Yes
37. Approved engineering drawings available	Not Inspected

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL

P1TJ-QJAP-426



Inspection Detail	
38. Approved operational plan available	Not Inspected
39. Approved stabilization/landscaping plan available	Not Inspected
40. Approved contingency plan available	Not Inspected
41. Approved groundwater monitoring plan available	Not Inspected
42. Approved closure/post-closure plan available	Not Inspected
43. Required records maintained	Not Inspected

Corrective Action

1. Corrective Action Due Date

Additional Comments

Record any additional information regarding the current activities at the site that has not already been captured in the previous questions

Stockpile of dirt at western slope, this was used for extra cover in an area where smell was identified, facility plans on adding berm here.

Photo Taken: 5/26/2026 1:10:00 PM
 GPS Latitude: 32.470311
 GPS Longitude: -80.650719
 GPS Altitude: 5.750000 meters
 GPS Orientation: 1 degrees

Signature	
Name of those present during inspection	Colin Scherer, Maci Dean

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL

P1TJ-QJAP-426



Signature

1. Facility Representative

A handwritten signature in black ink, appearing to read "Maci Dean".

1a. Facility Representative Name

Maci Dean

2. SCDES Inspector

A handwritten signature in black ink, appearing to read "Colin T. Scherer".

2a. SCDES Inspector Name

Colin T. Scherer

PRO DISPOSAL USA (BARNWELL RESOURCES)
CLASS 2 LANDFILL (P1TJ-QJAP-426)
Violation List

No Violations Found