

December 13, 2010

Town of Lexington
Attn: Allen Lutz
P.O. Box 397
Lexington, SC 29071

RE: Reinspection of Dam D-1717 Barr Lake Dam and D-0959, Gibson Pond Dam Lexington County

Dear Mr. Lutz:

This office performed a routine inspection of the Barr Lake Dam and Gibson Pond Dam on December 13, 2010. Enclosed you will find an inspection report which summarizes any comments or concerns.

Also enclosed is a copy of the Emergency Notification and Surveillance Plan. Please keep this in an easily accessible location so that all agencies can be notified as quickly as possible should the dam ever experience difficulty. Should the person responsible for implementing the plan change, our office must be notified immediately.

Provisions in the SC Dams and Reservoirs Safety Act require the owner to notify us within 30 days after transferring title or control of a dam to someone else. Enclosed is a form for your use should this transfer be necessary. Please note that this notification must include the name and address of any new owner.

If you need any assistance or have any questions prior to the next inspection, please do not hesitate to contact us at (803) 896-0620.

hauptmse@dhec.sc.gov.

Sincerely,



Steve Hauptmann, EIT
District Engineer Associate
Region 3 EQC-Columbia

Enclosures

INSPECTION REPORT

Date December 13, 2010

Dam D-1717, Barr Lake Dam Lexington County
D-0959, Gibson Pond Dam

Representatives of SCDHEC Present:

Steven Hauptmann

Representatives of Owner Present:

List of noted deficiencies or items requiring correction/checking:

Gibson Lake Dam:

- Debris and brush on West side of downslope inhibiting visual inspection-remove
- Dense vegetation of East side needs to be removed.
- Grass sod/seed should be laid on dam crest to reduce sediment erosion
- Water flowing under level boards noticed at time of inspection.

Barr Lake Dam:

- Vegetation on lower part of downstream side of dam impairs through inspection
- Unable to access outlet structure or make downstream pass due to heavy vegetation. Vegetation and brush should be removed
- It is recommended that additional rip rap or similar protection from water erosion be added at the sides of the spillway areas where wash out is present.
- No screen visible on inlet structure

Note: Dam should remain clear of vegetation year round.

Emergency Action Plan Updated

Yes _____ No X _____



Signature of Person Completing Form

**NOTIFICATION OF OWNERSHIP CHANGE
S.C. REGULATED DAM**

Date

The ownership of Dam D _____, _____ in

(Name of Dam)

_____ County has changed. The new owner(s) are:

Owner 1* _____

Address _____

City, State, Zip _____

Telephone Number _____

Owner 2* _____

(if applicable)

Address _____

City, State, Zip _____

Telephone Number _____

Additional Owner* _____

(if applicable)

Address _____

City, State, Zip _____

Telephone Number _____

*If owner is a corporation, give name of principal contact person:

(Previous Owner's Signature)

Previous Owner's Name

Previous Owners Address

Mail Above Notification To:

S.C. Department of Health and Environmental Control
Dams and Reservoirs Safety
2600 Bull Street
Columbia, SC 29201

NOTE: Failure to notify the S.C. Department of Health and Environmental Control within 30 days of ownership transfer can result in a fine of \$100 - \$1000.

DHEC 2605(6/94)