

Oct. 14, 2015:

DHEC teams are currently assessing Class One and Class Two dams statewide as a precaution after the historic rains and flooding. Since the beginning of the incident period, we've inspected 357 dams statewide so far.

As part of this proactive assessment, DHEC teams confirmed three unreported breaches on Wednesday in Orangeburg County.

- Culler Pond (SCNONAME 38070)
- Busbees Pond (Hutto's Millpond Dam)
- SCNONAME 38036 (Cleveland Street)

There is no risk to public safety from these breaches.

The dam status list will continue to be updated on our website as DHEC field teams complete these assessments.

Aiken County

Dam Name	Class*	Dam Number	Latitude	Longitude
Corbett Lake	C3	D2052	33.648651	-81.211333
SC NONAME 02019 (Bailey Pond)	C3	D2034	33.594676	-81.285939
Able/ Cobett Pond Dam	C3	D2048	33.62181631	-81.23376209

Clarendon County

Dam Name	Class*	Dam Number	Latitude	Longitude
O E Rose Dam	C2	D3487	33.80674348	-80.09057333
Lakewood Pond Dam	C2	D3490	33.7318223	-80.09334774

Darlington County

Dam Name	Class*	Dam Number	Latitude	Longitude
Chapman's Pond Dam	C2	D3533	34.42	-79.941666

Kershaw County

Dam Name	Class*	Dam Number	Latitude	Longitude
Cook Pond Dam	C2	D1068	34.15243939	-80.77560768

Lee County

Dam Name	Class*	Dam Number	Latitude	Longitude
Clyburn	C2	D2412	34.329886	-80.302055

Lexington County

Dam Name	Class*	Dam Number	Latitude	Longitude
Old Mill Pond Dam	C1	D0958	33.974641	-81.232641

Gibson's Pond Dam	C2	D0959	33.969067	-81.244925
Barr Lake Dam	C2	D1717	33.958512	-81.259604

Orangeburg County

Dam Name	Class*	Dam Number	Latitude	Longitude
JW Smoaks Pond	C2	D3738	33.525181	-80.934540
Culler Pond (SCNONAME 38070)	C3	D3682	33.63670829	-81.15938027
Busbees Pond (Hutto's Millpond Dam)	C2	D3701	33.55656622	-81.05704327
SCNONAME 38036 (Cleveland Street)	C3	D 3743	33.52294114	-80.51387012

Richland County

Dam Name(s)	Class*	Dam Number	Latitude	Longitude
Cary's Lake Dam	C1	D0026	34.048873	-80.957954
Upper Rocky Creek/ North Lake/Overcreek Rd.	C1	D0029	34.040808	-80.951982
Lower Rocky Ford Dam /Rocky Ford Lake	C1	D0028	34.036033	-80.952343
Semmes Lake Dam	Federal	Fort Jackson	34.004763	-80.941769
Beaver Dam/Wildewood Pond #2/Boyd Pond Two (Controlled release)	C2	D0567	34.096382	-80.886478
Lake Elizabeth	C1	D 0024	34.113028	-80.987693
Ulmers Pond	C1	D0581	33.968661	-80.895350
Sunview Lake Dam	C2	D0579	33.96735	-80.91163
Walden Place Dam	C1	D0572	34.11678	-80.84591
Pinewood Lake Dam	C2	D0580	33.94404929	-80.91198374
Covington Lake Dam	C2	D0545	34.13463666	-80.97464885
Murray Pond Dam	C2	D0595	33.98543068	-80.70793299
Wilson Millpond Dam	C2	D0594	33.99992669	-80.74288775
Weston Pond Dam	C3	D0593	33.883093	-80.768417
Clarkson Pond Dam	C3	D0599	33.870060	-80.826624
Duffies Pond Dam	C2	D0600	33.84433294	-80.85269049

Sumter County

Dam Name	Class*	Dam Number	Latitude	Longitude
Ellerbees Millpond Dam	C2	D1460	34.06843763	-80.53162143

Also in Richland County: Dike breach at Columbia Canal

* What the dam classifications mean:

C1 – Failure may cause loss of life or serious damage to infrastructure.

C2 – Failure will not likely cause loss of life but may damage infrastructure.

C3 – Failure may cause limited property damage.