



Catherine E. Heigel, Director

*Promoting and protecting the health of the public and the environment*

July 29, 2015

Mr. Jay Smith, P.E.  
Phillips North America  
15313 West 95<sup>th</sup> Street  
Lenexa, Kansas 66219

Re: Summary of Investigation Efforts dated 11-3-14  
Additional Well Summary Table dated 6-2-15  
Former Shakespeare Composite Structures Site  
Newberry County  
Voluntary Cleanup Contract 14-6271-RP  
File #51025


Dear Mr. Smith,

The Department has reviewed the referenced documents and offers the following comments.

1. No boring logs, well construction diagrams or 1903 forms were included in the referenced submittal for temporary wells TMW-1 – TMW-8.
2. No 1903 forms were included in the report for temporary wells TMW-35(35), TMW-36, TMW-48, TMW-49, TMW-103, TMW107, TMW-108 and TMW-109.
3. The first folder on the data disk is data from the Admiral Home Site and not the Shakespeare Site.
4. The Well Summary Table submitted to the Department on June 2, 2015 should be added to this report and the document revised accordingly.

Please submit these omissions/revisions, to my attention, on or before August 31, 2015. Also, please title the next assessment report "Remedial Investigation Phase \_\_\_\_". Please feel free to contact me with any questions or comments at (803) 898-0722 or at [walkeras@dhec.sc.gov](mailto:walkeras@dhec.sc.gov).

Sincerely,



Addie Walker, Hydrologist

State Remediation Section  
Bureau of Land and Waste Management

CC: Gary Stewart, BLWM  
Harry Mathis, Director, Midlands Region EQC  
Scott Ross, AECOM, 101 Research Drive, Columbia, SC 29203  
File #51025