

# PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL



P1TJ-QJAP-426

Inspector: Colin Sherer

Start Date: 12/17/2025      Completed Date: 12/17/2025

## Solid Waste - Class 2 Landfill

### Facility

#### Facility Name

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL

#### Date of Inspection

12/17/2025

#### Time of Inspection

11:01 AM

#### County

Beaufort

#### Permit #

### Inspection Processing

#### Reason for Inspection

Routine

#### Weather Conditions

Cloudy

#### Temperature

50s

#### Rainfall in past week

0-0.5

#### Weather Condition Description

#### Last Inspection

11/12/2025

### Inspection Detail

#### 1. Attendant Present

Yes

#### 2. Required signs posted

Yes

#### 3. Inspection of all incoming loads conducted

Yes

#### 4. Unauthorized waste training conducted and documented

Not Inspected

#### 5. No unauthorized waste present

Yes

#### 6. Access controlled

Yes

#### 7. Adequate entrance all-weather roads

Yes

#### 8. Adequate internal all-weather haul roads

Yes

#### 9. Frequency of cover meets regulatory/ permit requirements

Yes

#### 10. > Six inches of soil (short-term cover) meets regulatory/permit requirements

Yes

# PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL



P1TJ-QJAP-426

Inspector: Colin Sherer

Start Date: 12/17/2025      Completed Date: 12/17/2025

## Inspection Detail

<b>11. Approved Alternate Monthly Cover (AMC) used</b>	Not Applicable
<b>12. &gt; Six inches of soil (long-term and/or intermediate cover) meets regulatory/permit requirements</b>	Yes
<b>13. Adequate soil quantity available for cover</b>	Yes
<b>14. Working face slope does not exceed 3:1</b>	Yes
<b>15. Waste spread in uniform layers and compacted to smallest practical volume</b>	Yes
<b>16. Working face as small as can efficiently and safely be managed</b>	Yes



Photo Taken: 12/17/2025 4:15:00 PM  
GPS Latitude: 32.471395  
GPS Longitude: 80.649378



Photo Taken: 12/17/2025 4:21:00 PM  
GPS Latitude: 32.470980  
GPS Longitude: 80.648637

# PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL



P1TJ-QJAP-426

Inspector: Colin Sherer

Start Date: 12/17/2025      Completed Date: 12/17/2025

## Inspection Detail

<b>17. Asbestos containing material adequately handled</b>	Not Applicable
<b>18. Dead animals adequately handled</b>	Not Applicable
<b>19. All required equipment operational</b>	Yes
<b>20. Access to fire equipment and fire fighting services</b>	Yes
<b>21. Disposal area graded to a minimum 1% slope</b>	Yes
<b>22. Adequate condition of ditches/swales</b>	Yes

# PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL



P1TJ-QJAP-426

Inspector: Colin Sherer

Start Date: 12/17/2025      Completed Date: 12/17/2025

## Inspection Detail

### 23. Adequate condition of berms/terraces/downchutes

Yes

#### Comments:

Eastern slope seeded, grass has been slow to grow with recent cold weather



Photo Taken: 12/17/2025 4:16:00 PM  
GPS Latitude: 32.471192  
GPS Longitude: 80.648580




Photo Taken: 12/17/2025 4:16:00 PM  
GPS Latitude: 32.471192  
GPS Longitude: 80.648580

### 24. Adequate condition of sedimentation ponds

Yes

### 25. Control of Dust

Yes

### 26. Control of Litter

Yes

# PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL



P1TJ-QJAP-426

Inspector: Colin Sherer

Start Date: 12/17/2025      Completed Date: 12/17/2025

## Inspection Detail

<b>27. Control of Odors</b>	No
<b>Comments:</b> H2S smell on upper deck. Smell was not as prominent coming in on Middle Rd as last inspection	
<b>28. Control of Vectors</b>	Yes
<b>29. Control of Fires/Open Burning</b>	Yes
<b>30. Scales installed and functioning properly</b>	Yes
<b>31. Scales calibrated adequately</b>	Not Inspected
<b>32. Monitoring well pads are free of sediment buildup and standing water</b>	Not Inspected
<b>33. Monitoring wells pads are free of cracks</b>	Not Inspected
<b>34. Monitoring wells are labeled</b>	Not Inspected
<b>35. Monitoring wells are locked</b>	Not Inspected
<b>36. Operating in accordance with approved plans</b>	Not Inspected
<b>37. Approved engineering drawings available</b>	Not Inspected
<b>38. Approved operational plan available</b>	Not Inspected
<b>39. Approved stabilization/landscaping plan available</b>	Not Inspected
<b>40. Approved contingency plan available</b>	Not Inspected
<b>41. Approved groundwater monitoring plan available</b>	Not Inspected
<b>42. Approved closure/post-closure plan available</b>	Not Inspected
<b>43. Required records maintained</b>	Not Inspected
<b>Corrective Action</b>	
<b>1. Corrective Action Due Date</b>	

# PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL



P1TJ-QJAP-426

Inspector: Colin Sherer

Start Date: 12/17/2025      Completed Date: 12/17/2025

## Additional Comments

**Record any additional information regarding the current activities at the site that has not already been captured in the previous questions**

Highest section of the landfill has had additional soil cover. Working face has been relocated to top deck of landfill and previous lower working face is being covered. Should be fully covered by end of week. Facility plans to work on upper deck until final elevation is reached and final cap can be placed, graded, seeded, and down chutes installed. Progress on submitted odor abatement plan is moving along on schedule.

# PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL



P1TJ-QJAP-426

Inspector: Colin Sherer

Start Date: 12/17/2025      Completed Date: 12/17/2025

## Additional Comments



Photo Taken: 12/17/2025 4:11:00 PM  
GPS Latitude: 32.471395  
GPS Longitude: 80.649378




Photo Taken: 12/17/2025 4:23:00 PM  
GPS Latitude: 32.470730  
GPS Longitude: 80.648720




Photo Taken: 12/17/2025 4:43:00 PM  
GPS Latitude: 32.474862  
GPS Longitude: 80.649292

# PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL



P1TJ-QJAP-426

Inspector: Colin Scherer

Start Date: 12/17/2025      Completed Date: 12/17/2025

## Signature

### Name of those present during inspection

Chris Moak, Chris Carney, Maci Dean, Colin Scherer

### 1. Facility Representative

A handwritten signature of Maci Dean.

#### 1a. Facility Representative Name

Maci Dean

### 2. SCDES Inspector

A handwritten signature of Colin T. Scherer.

#### 2a. SCDES Inspector Name

Colin T. Scherer

PRO DISPOSAL USA (BARNWELL RESOURCES)  
CLASS 2 LANDFILL (P1TJ-QJAP-426)  
Violation List

No Violations Found