USTPREPA - EPA PUBLIC REPORT

GENERAL INFORMATION	Total Number of UST Facilities	Total Number of USTs
	3957	11057

SUMMARY INFORMATION FOR ON-SITE INSPECTIONS	Inspection Period Date	Number of UST Facilities Inspected	Percent Compliance
	10/01/2025 - 09/30/2026	3474	60.33%

SUMMARY INFORMATION FOR RELEASES	Release Reporting Period Date	Number of Confirmed UST Releases
	10/01/2025 - 09/30/2026	111

NOTE: Tank, facility, and on-site inspection information is based on underground storage tanks regulated under Subtitle I that satisfy the definition of UST in 40 CFR 280.12, except for those tanks identified in 40 CFR 280.10(b) as excluded USTs and those deferred in 40 CFR 280.10(c). On-site inspections measure compliance with release detection and release prevention (technical compliance rate, state regulations, Subtitle I, etc.).

SUMMARY INFORMATION FOR RELEASE SOURCES AND CAUSES :

Source	1. Spill		2. Overfill		3. Physical or Mechanical Damage		4. Corrosion		5. Installation Problem		6. Other		7. Unknown		Total	
Location	#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%
1.TANK	0	0.00%	0	0.00%	2	1.80%	0	0.00%	0	0.00%	31	27.93%	1	0.90%	**34**	**30.63%**
2. PIPING	0	0.00%	0	0.00%	5	4.50%	0	0.00%	0	0.00%	0	0.00%	0	0.00%	**5**	**4.50%**
3. DISPENSER	0	0.00%	0	0.00%	7	6.31%	0	0.00%	0	0.00%	0	0.00%	0	0.00%	**7**	**6.31%**
4. STP	0	0.00%	0	0.00%	6	5.41%	0	0.00%	0	0.00%	0	0.00%	0	0.00%	**6**	**5.41%**
6. OVERFILL	0	0.00%	1	0.90%	0	0.00%	0	0.00%	0	0.00%	0	0.00%	0	0.00%	**1**	**0.90%**
7. OTHER	0	0.00%	0	0.00%	47	42.34%	0	0.00%	0	0.00%	10	9.01%	0	0.00%	**57**	**51.35%**
8. UNKNOWN	0	0.00%	0	0.00%	0	0.00%	0	0.00%	0	0.00%	1	0.90%	0	0.00%	**1**	**0.90%**
Total	**0**	**0.00%**	**1**	**0.90%**	**67**	**60.36%**	**0**	**0.00%**	**0**	**0.00%**	**42**	**37.84%**	**1**	**0.90%**	**111**	**100.00%**

NOTE: Release, source and cause information is based on underground storage tanks regulated under Subtitle I that satisfy the definition of UST in 40 CFR 280.12. This report reflects data from releases reported to the Department during the time period of the report. So urce and cause data were collected using on-site inspections and reports from facilities.

NOTE: "UNKNOWN" is based on releases discovered during tank removal operations or pre-buy assessments. The locations of these releases were not identifiable. "OTHER" is an identifiable source that does not fit specific locations identified in the chart.

Additional information on site-specific USTs such as compliance and releases may be obtained through contacting the Freedom of Information Office at 803-898-3880 or on-line at the UST Registry (https://des.sc.gov/).