

General Information

Total Number Of UST Facilities: 3,938
 Total Number Of USTs: 11,019

Summary Information For On-Site Inspections

Number Of UST Facilities Inspected: 2,902
 Inspection Period Dates: 10/01/2023 To: 10/01/2024
 Percent Compliance (Combined Measure): 54.72 %

Note: Tank, facility, and on-site inspection information is based on underground storage tanks regulated under Subtitle I that satisfy the definition of UST in 40 CFR 280.12, except for those tanks identified in 40 CFR 280.10(b) as excluded USTs and those deferred in 40 CFR 280.10(c). On-site inspections measure compliance with release detection and release prevention (technical compliance rate, state regulations, Subtitle I, etc.).

Summary Information For Releases:

Number Of Confirmed UST Releases: 98
 Release Reporting Period Dates: 10/01/2023 To: 10/01/2024

Summary Information For Release Sources And Causes:

| Source/Location | | | Cause | | | | | | | | | | | | | |
|----------------------|----|-------|-------|------|----------|------|------------------|--------|-----------|------|-----------------|------|-------|--------|---------|------|
| | | | Spill | | Overfill | | Phys/Mech Damage | | Corrosion | | Install Problem | | Other | | Unknown | |
| # | % | # | % | # | % | # | % | # | % | # | % | # | % | # | % | |
| TANK | 27 | 27.55 | 0 | 0.00 | 0 | 0.00 | 1 | 3.70 | 0 | 0.00 | 0 | 0.00 | 26 | 96.30 | 0 | 0.00 |
| PIPING | 10 | 10.20 | 0 | 0.00 | 0 | 0.00 | 10 | 100.00 | 0 | 0.00 | 0 | 0.00 | 0 | 0.00 | 0 | 0.00 |
| DISPENSER | 13 | 13.27 | 0 | 0.00 | 0 | 0.00 | 13 | 100.00 | 0 | 0.00 | 0 | 0.00 | 0 | 0.00 | 0 | 0.00 |
| STP | 6 | 6.12 | 0 | 0.00 | 0 | 0.00 | 6 | 100.00 | 0 | 0.00 | 0 | 0.00 | 0 | 0.00 | 0 | 0.00 |
| DELIVERY PROB | 0 | 0.00 | 0 | 0.00 | 0 | 0.00 | 0 | 0.00 | 0 | 0.00 | 0 | 0.00 | 0 | 0.00 | 0 | 0.00 |
| OVERFILL | 0 | 0.00 | 0 | 0.00 | 0 | 0.00 | 0 | 0.00 | 0 | 0.00 | 0 | 0.00 | 0 | 0.00 | 0 | 0.00 |
| OTHER | 41 | 41.84 | 0 | 0.00 | 0 | 0.00 | 32 | 78.05 | 0 | 0.00 | 0 | 0.00 | 9 | 21.95 | 0 | 0.00 |
| UNKNOWN | 1 | 1.02 | 0 | 0.00 | 0 | 0.00 | 0 | 0.00 | 0 | 0.00 | 0 | 0.00 | 1 | 100.00 | 0 | 0.00 |
| Totals | 98 | | 0 | 0.00 | 0 | 0.00 | 62 | 63.27 | 0 | 0.00 | 0 | 0.00 | 36 | 36.73 | 0 | 0.00 |

Note: **Release, source and cause** information is based on underground storage tanks regulated under Subtitle I that satisfy the definition of UST in 40 CFR 280.12. This report reflects data from releases reported to the Department during the time period of the report. Source and cause data were collected using on-site inspections and reports from facilities.

Note: **"UNKNOWN"** is based on releases discovered during tank removal operations or pre-buy assessments. The locations of these releases were not identifiable. **"OTHER"** is an identifiable source that does not fit specific locations identified in the chart.

Additional information on site-specific USTs such as compliance and releases may be obtained through contacting the Freedom of Information Office at 803-898-3880 or on-line at the UST Registry (WWW.SCDES.GOV)