

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL



P1TJ-QJAP-426

Inspector: Colin Scherer

Start Date: 04/20/2026 Completed Date: 04/20/2026

| Solid Waste - Class 2 Landfill | |
|--|--|
| Facility | |
| Facility Name | PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL |
| Date of Inspection | 4/20/2026 |
| Time of Inspection | 11:10 AM |
| County | Beaufort |
| Permit # | 072410-1201 |
| Inspection Processing | |
| Reason for Inspection | Routine |
| Weather Conditions | Sunny |
| Temperature | 60s |
| Rainfall in past week | 0-0.5 |
| Weather Condition Description | Extreme drought conditions |
| Last Inspection | 03/19/2026 |
| Inspection Detail | |
| 1. Attendant Present | Yes |
| 2. Required signs posted | Yes |
| 3. Inspection of all incoming loads conducted | Yes |
| 4. Unauthorized waste training conducted and documented | Not Inspected |
| 5. No unauthorized waste present | Yes |
| 6. Access controlled | Yes |
| 7. Adequate entrance all-weather roads | Yes |
| 8. Adequate internal all-weather haul roads | Yes |

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL




P1TJ-QJAP-426

Inspector: Colin Scherer

Start Date: 04/20/2026 Completed Date: 04/20/2026

Inspection Detail

| | |
|---|----------------|
| 9. Frequency of cover meets regulatory/ permit requirements | Yes |
| <p><i>Comments:</i> Entire last month's working face was covered as of 04/15/2026.</p> | |
| 10. > Six inches of soil (short-term cover) meets regulatory/permit requirements | Yes |
| 11. Approved Alternate Monthly Cover (AMC) used | Not Applicable |
| 12. > Six inches of soil (long-term and/or intermediate cover) meets regulatory/permit requirements | Yes |
| 13. Adequate soil quantity available for cover | Yes |
| 14. Working face slope does not exceed 3:1 | Yes |
| 15. Waste spread in uniform layers and compacted to smallest practical volume | Yes |
| 16. Working face as small as can efficiently and safely be managed | Yes |
| <div style="display: flex; align-items: flex-start;"> <div style="flex: 1;">  </div> <div style="flex: 1; padding-left: 20px;"> <p>Photo Taken: 04/20/2026 11:17:00 AM GPS Latitude: 32.47346388888894 GPS Longitude: -80.64790277777779 GPS Altitude: 9.6 meters GPS Orientation: 1 degrees</p> </div> </div> | |
| 17. Asbestos containing material adequately handled | Not Applicable |
| 18. Dead animals adequately handled | Not Applicable |

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL



P1TJ-QJAP-426

Inspector: Colin Scherer

Start Date: 04/20/2026 Completed Date: 04/20/2026

Inspection Detail

19. All required equipment operational Yes

Comments:

Excavator with magnet for separating metals for recycling is down, repair should be complete tomorrow.

20. Access to fire equipment and fire fighting services Yes

21. Disposal area graded to a minimum 1% slope Yes

22. Adequate condition of ditches/swales Yes

23. Adequate condition of berms/terraces/downchutes Yes

24. Adequate condition of sedimentation ponds Yes

25. Control of Dust Yes

Comments:

Drought conditions contributing to dust along internal roads from truck traffic. Facility is wetting the entrance for dust suppression and working on getting a water truck to wet internal roads.

26. Control of Litter No

Comments:

Litter fences have been installed up top adjacent to working face, but wind blown litter in ditches is still significant.



Photo Taken: 04/20/2026 11:24:00 AM
 GPS Latitude: 32.47134444444445
 GPS Longitude: -80.64885555555556
 GPS Altitude: 25.41 meters
 GPS Orientation: 1 degrees

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL



P1TJ-QJAP-426

Inspector: Colin Scherer

Start Date: 04/20/2026

Completed Date: 04/20/2026

Inspection Detail



Photo Taken: 04/20/2026 11:37:00 AM
GPS Latitude: 32.47016388888889
GPS Longitude: -80.65061111111112
GPS Altitude: 4.79 meters
GPS Orientation: 1 degrees



Photo Taken: 04/20/2026 11:37:00 AM
GPS Latitude: 32.47016388888889
GPS Longitude: -80.65061111111112
GPS Altitude: 4.79 meters
GPS Orientation: 1 degrees



Photo Taken: 04/20/2026 11:41:00 AM
GPS Latitude: 32.46866111111111
GPS Longitude: -80.64749722222223
GPS Altitude: 7.79 meters
GPS Orientation: 1 degrees

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL



P1TJ-QJAP-426

Inspector: Colin Scherer

Start Date: 04/20/2026 Completed Date: 04/20/2026

Inspection Detail



Photo Taken: 04/20/2026 11:41:00 AM
 GPS Latitude: 32.46866111111111
 GPS Longitude: -80.64749722222223
 GPS Altitude: 7.79 meters
 GPS Orientation: 1 degrees

| | |
|--|---------------|
| 27. Control of Odors | Yes |
| <i>Comments:</i> H2S odor was not detected along Middle Rd. prior to inspection. Slight odor at working face. | |
| 28. Control of Vectors | Yes |
| 29. Control of Fires/Open Burning | Yes |
| 30. Scales installed and functioning properly | Yes |
| 31. Scales calibrated adequately | Yes |
| ▶ 31a. Last date of calibration | 5/01/2025 |
| 32. Monitoring well pads are free of sediment buildup and standing water | Not Inspected |
| 33. Monitoring wells pads are free of cracks | Not Inspected |
| 34. Monitoring wells are labeled | Not Inspected |

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL



P1TJ-QJAP-426

Inspector: Colin Scherer

Start Date: 04/20/2026 Completed Date: 04/20/2026

Inspection Detail

35. Monitoring wells are locked Yes

Comments:

MW4 noted on last inspection is now locked. New locks on all wells have been installed.



Photo Taken: 04/20/2026 11:35:00 AM
 GPS Latitude: 32.4726027777778
 GPS Longitude: -80.6512
 GPS Altitude: 5.22 meters
 GPS Orientation: 1 degrees

36. Operating in accordance with approved plans Yes

37. Approved engineering drawings available Not Inspected

38. Approved operational plan available Not Inspected

39. Approved stabilization/landscaping plan available Not Inspected

40. Approved contingency plan available Not Inspected

41. Approved groundwater monitoring plan available Not Inspected

42. Approved closure/post-closure plan available Not Inspected

43. Required records maintained Not Inspected

Corrective Action

1. Corrective Action Due Date 5/20/2026

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL



P1TJ-QJAP-426

Inspector: Colin Scherer

Start Date: 04/20/2026 Completed Date: 04/20/2026

Additional Comments

Record any additional information regarding the current activities at the site that has not already been captured in the previous questions

Bare slopes have been hydroseeded and facility has done some manual watering, but lack of rain is making growth slow. Working face will be moved soon to the south end of the landfill peak. Operator states they have chosen a contractor for a gas management system, with final plans due to be presented to Solid Waste and Air teams in Columbia soon for approval.



Photo Taken: 04/20/2026 11:21:00 AM
GPS Latitude: 32.470688888888894
GPS Longitude: -80.64880277777779
GPS Altitude: 18.3 meters
GPS Orientation: 1 degrees



Photo Taken: 04/20/2026 11:22:00 AM
GPS Latitude: 32.470688888888894
GPS Longitude: -80.64880277777779
GPS Altitude: 18.3 meters
GPS Orientation: 1 degrees

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL



P1TJ-QJAP-426

Inspector: Colin Scherer

Start Date: 04/20/2026 Completed Date: 04/20/2026

Additional Comments



Photo Taken: 04/20/2026 11:22:00 AM
 GPS Latitude: 32.470688888888894
 GPS Longitude: -80.64880277777779
 GPS Altitude: 18.3 meters
 GPS Orientation: 1 degrees



Photo Taken: 04/20/2026 11:37:00 AM
 GPS Latitude: 32.470163888888889
 GPS Longitude: -80.65061111111112
 GPS Altitude: 4.79 meters
 GPS Orientation: 1 degrees

Signature

| | |
|--|--------------------------|
| Name of those present during inspection | Maci Dean, Colin Scherer |
| 1. Facility Representative | |
| 1a. Facility Representative Name | Maci Dean |
| 2. SCDES Inspector | |
| 2a. SCDES Inspector Name | Colin T. Scherer |

PRO DISPOSAL USA (BARNWELL RESOURCES)
CLASS 2 LANDFILL (P1TJ-QJAP-426)
Violation List

No Violations Found