

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL



P1TJ-QJAP-426

Inspector: Colin Sherer

Start Date: 02/12/2026 Completed Date: 02/12/2026

Solid Waste - Class 2 Landfill	
Facility	
Facility Name	PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL
Date of Inspection	2/12/2026
Time of Inspection	1:55 PM
County	Beaufort
Permit #	072410-1201
Inspection Processing	
Reason for Inspection	Routine
Weather Conditions	Sunny
Temperature	60s
Rainfall in past week	0-0.5
Weather Condition Description	
Last Inspection	01/21/2026
Inspection Detail	
1. Attendant Present	Yes
2. Required signs posted	Yes
3. Inspection of all incoming loads conducted	Yes
4. Unauthorized waste training conducted and documented	Not Inspected
5. No unauthorized waste present	Yes
6. Access controlled	Yes
7. Adequate entrance all-weather roads	Yes
8. Adequate internal all-weather haul roads	Yes

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL



P1TJ-QJAP-426

Inspector: Colin Sherer

Start Date: 02/12/2026 Completed Date: 02/12/2026

Inspection Detail	
9. Frequency of cover meets regulatory/ permit requirements	Yes
<i>Comments:</i> Last cover 1.5 weeks ago	
10. > Six inches of soil (short-term cover) meets regulatory/permit requirements	Yes
11. Approved Alternate Monthly Cover (AMC) used	Not Applicable
12. > Six inches of soil (long-term and/or intermediate cover) meets regulatory/permit requirements	Yes
13. Adequate soil quantity available for cover	Yes
14. Working face slope does not exceed 3:1	Yes

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL



P1TJ-QJAP-426

Inspector: Colin Sherer

Start Date: 02/12/2026 Completed Date: 02/12/2026

Inspection Detail

15. Waste spread in uniform layers and compacted to smallest practical volume Yes



Photo Taken: 02/12/2026 02:00:00 PM
 GPS Latitude: 32.47169444444445
 GPS Longitude: -80.6494305555557
 GPS Altitude: 26.26 meters
 GPS Orientation: 1 degrees



Photo Taken: 02/12/2026 02:09:00 PM
 GPS Latitude: 32.47173333333333
 GPS Longitude: -80.64951388888889
 GPS Altitude: 20.3 meters
 GPS Orientation: 1 degrees

16. Working face as small as can efficiently and safely be managed Yes

17. Asbestos containing material adequately handled Not Applicable

18. Dead animals adequately handled Not Applicable

19. All required equipment operational Yes

20. Access to fire equipment and fire fighting services Yes

21. Disposal area graded to a minimum 1% slope Yes

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL



P1TJ-QJAP-426

Inspector: Colin Sherer

Start Date: 02/12/2026 Completed Date: 02/12/2026

Inspection Detail	
22. Adequate condition of ditches/swales	Yes
23. Adequate condition of berms/terraces/downchutes	Yes
<i>Comments:</i> Seeded slopes should be growing grass by springtime warmer weathers for erosion control.	
24. Adequate condition of sedimentation ponds	Yes
25. Control of Dust	Yes
26. Control of Litter	Yes
27. Control of Odors	No
<i>Comments:</i> Some H2S smell at workin face. Smell was not detectable along Middle Rd. while driving to the site.	
28. Control of Vectors	Yes
29. Control of Fires/Open Burning	Yes
30. Scales installed and functioning properly	Yes
31. Scales calibrated adequately	Not Inspected
32. Monitoring well pads are free of sediment buildup and standing water	Not Inspected
33. Monitoring wells pads are free of cracks	Not Inspected
34. Monitoring wells are labeled	Not Inspected
35. Monitoring wells are locked	Not Inspected
36. Operating in accordance with approved plans	Yes
37. Approved engineering drawings available	Not Inspected
38. Approved operational plan available	Not Inspected
39. Approved stabilization/landscaping plan available	Not Inspected
40. Approved contingency plan available	Not Inspected

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL



P1TJ-QJAP-426

Inspector: Colin Sherer

Start Date: 02/12/2026 Completed Date: 02/12/2026

Inspection Detail	
41. Approved groundwater monitoring plan available	Not Inspected
42. Approved closure/post-closure plan available	Not Inspected
43. Required records maintained	Not Inspected
Corrective Action	
1. Corrective Action Due Date	

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL



P1TJ-QJAP-426

Inspector: Colin Sherer

Start Date: 02/12/2026 Completed Date: 02/12/2026

Additional Comments

Record any additional information regarding the current activities at the site that has not already been captured in the previous questions

New ramp being built for access to top of landfill before new waste is diverted there. Tarp is now on site for end of day cover of truck turn-around area beside working face. Tarp will be applied at the end of each working day for overnight cover and removed in mornings. The gas monitoring project data has been sent off and the facility should have a decision on gas management going forward by next week.



Photo Taken: 02/12/2026 02:02:00 PM
GPS Latitude: 32.4718888888889
GPS Longitude: -80.64938333333335
GPS Altitude: 25.77 meters
GPS Orientation: 1 degrees



Photo Taken: 02/12/2026 02:04:00 PM
GPS Latitude: 32.4718888888889
GPS Longitude: -80.64938333333335
GPS Altitude: 25.77 meters
GPS Orientation: 1 degrees

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL



P1TJ-QJAP-426

Inspector: Colin Sherer

Start Date: 02/12/2026 Completed Date: 02/12/2026

Additional Comments

Feb 12, 2026 at 2:19:09 PM
490 Brickyard Point Rd S
Beaufort SC 29907
United States

TABLE 1: MONITORING RESULTS
ODOR ASSESSMENT PLAN

DATE	MONITORING RESULTS										
	1	2	3	4	5	6	7	8	9	10	11
1-26-26	0	0	0	0	0	0	0	0	0	0	0
Morning	0	0	0	0	0	0	0	0	0	0	0
Afternoon	0	0	0	0	0	0	0	0	0	0	0
1-27-26	0	0	0	0	0	0	0	0	0	0	0
Morning	0	0	0	0	0	0	0	0	0	0	0
Afternoon	0	0	0	0	0	0	0	0	0	0	0
1-28-26	0	0	0	0	0	0	0	0	0	0	0
Morning	0	0	0	0	0	0	0	0	0	0	0
Afternoon	0	0	0	0	0	0	0	0	0	0	0
1-29-26	0	0	0	0	0	0	0	0	0	0	0
Morning	0	0	0	0	0	0	0	0	0	0	0
Afternoon	0	0	0	0	0	0	0	0	0	0	0
1-30-26	0	0	0	0	0	0	0	0	0	0	0
Morning	0	0	0	0	0	0	0	0	0	0	0
Afternoon	0	0	0	0	0	0	0	0	0	0	0
Morning											
Afternoon											

Photo Taken: 02/12/2026 02:19:00 PM
GPS Latitude: 32.47481388888889
GPS Longitude: -80.64927777777778
GPS Altitude: 1.25 meters
GPS Orientation: 1 degrees

Feb 12, 2026 at 2:19:17 PM
490 Brickyard Point Rd S
Beaufort SC 29907
United States

TABLE 1: MONITORING RESULTS
ODOR ASSESSMENT PLAN

DATE	MONITORING RESULTS										
	1	2	3	4	5	6	7	8	9	10	11
2-2-26	0	0	0	0	0	0	0	0	0	0	0
Morning	0	0	0	0	0	0	0	0	0	0	0
Afternoon	0	0	0	0	0	0	0	0	0	0	0
2-3-26	0	0	0	0	0	0	0	0	0	0	0
Morning	0	0	0	0	0	0	0	0	0	0	0
Afternoon	0	0	0	0	0	0	0	0	0	0	0
2-4-26	0	0	0	0	0	0	0	0	0	0	0
Morning	0	0	0	0	0	0	0	0	0	0	0
Afternoon	0	0	0	0	0	0	0	0	0	0	0
2-5-26	0	0	0	0	0	0	0	0	0	0	0
Morning	0	0	0	0	0	0	0	0	0	0	0
Afternoon	0	0	0	0	0	0	0	0	0	0	0
2-6-26	0	0	0	0	0	0	0	0	0	0	0
Morning	0	0	0	0	0	0	0	0	0	0	0
Afternoon	0	0	0	0	0	0	0	0	0	0	0
Morning											
Afternoon											

Photo Taken: 02/12/2026 02:19:00 PM
GPS Latitude: 32.47481388888889
GPS Longitude: -80.64927777777778
GPS Altitude: 1.25 meters
GPS Orientation: 1 degrees

Feb 12, 2026 at 2:19:26 PM
490 Brickyard Point Rd S
Beaufort SC 29907
United States

TABLE 1: MONITORING RESULTS
ODOR ASSESSMENT PLAN

DATE	MONITORING RESULTS										
	1	2	3	4	5	6	7	8	9	10	11
2-9-26	0	0	0	0	0	0	0	0	0	0	0
Morning	0	0	0	0	0	0	0	0	0	0	0
Afternoon	0	0	0	0	0	0	0	0	0	0	0
2-10-26	0	0	0	0	0	0	0	0	0	0	0
Morning	0	0	0	0	0	0	0	0	0	0	0
Afternoon	0	0	0	0	0	0	0	0	0	0	0
2-11-26	0	0	0	0	0	0	0	0	0	0	0
Morning	0	0	0	0	0	0	0	0	0	0	0
Afternoon	0	0	0	0	0	0	0	0	0	0	0
2-12-26	0	0	0	0	0	0	0	0	0	0	0
Morning	0	0	0	0	0	0	0	0	0	0	0
Afternoon	0	0	0	0	0	0	0	0	0	0	0
2-13-26											
Morning											
Afternoon											
Morning											
Afternoon											

Photo Taken: 02/12/2026 02:19:00 PM
GPS Latitude: 32.47481388888889
GPS Longitude: -80.64927777777778
GPS Altitude: 1.25 meters
GPS Orientation: 1 degrees

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL



P1TJ-QJAP-426

Inspector: Colin Scherer

Start Date: 02/12/2026 Completed Date: 02/12/2026

Signature	
Name of those present during inspection	
Maci Dean, Megan Maule, Colin Scherer	
1. Facility Representative	
1a. Facility Representative Name	Maci Dean
2. SCDES Inspector	
2a. SCDES Inspector Name	Colin T. Scherer

PRO DISPOSAL USA (BARNWELL RESOURCES)
CLASS 2 LANDFILL (P1TJ-QJAP-426)
Violation List

No Violations Found