

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL



P1TJ-QJAP-426

Inspector: Colin Scherer

Start Date: 03/19/2026 Completed Date: 03/19/2026

Solid Waste - Class 2 Landfill Facility	
Facility Name	PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL
Date of Inspection	3/19/2026
Time of Inspection	1:23 PM
County	Beaufort
Permit #	072410-1201
Inspection Processing	
Reason for Inspection	Routine
Weather Conditions	Sunny
Temperature	60s
Rainfall in past week	0-0.5
Weather Condition Description	Heavy wind in past week.
Last Inspection	02/12/2026
Inspection Detail	
1. Attendant Present	Yes
2. Required signs posted	Yes
3. Inspection of all incoming loads conducted	Yes
4. Unauthorized waste training conducted and documented	Yes
5. No unauthorized waste present	Yes
6. Access controlled	Yes
7. Adequate entrance all-weather roads	Yes
8. Adequate internal all-weather haul roads	Yes
9. Frequency of cover meets regulatory/ permit requirements	Yes
10. > Six inches of soil (short-term cover) meets regulatory/permit requirements	Yes

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL



P1TJ-QJAP-426

Inspector: Colin Scherer

Start Date: 03/19/2026 Completed Date: 03/19/2026

Inspection Detail

11. Approved Alternate Monthly Cover (AMC) used Not Applicable

12. > Six inches of soil (long-term and/or intermediate cover) meets regulatory/permit requirements Yes

13. Adequate soil quantity available for cover Yes



Photo Taken: 03/19/2026 01:47:00 PM
 GPS Latitude: 32.47099444444444
 GPS Longitude: -80.64906944444445
 GPS Altitude: 21.23 meters
 GPS Orientation: 1 degrees

14. Working face slope does not exceed 3:1 Yes

15. Waste spread in uniform layers and compacted to smallest practical volume Yes

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL



P1TJ-QJAP-426

Inspector: Colin Scherer

Start Date: 03/19/2026

Completed Date: 03/19/2026

Inspection Detail



Mar 19, 2026 at 1:48:02 PM
Beaufort SC 29907
United States
Lady's Island

Photo Taken: 03/19/2026 01:48:00 PM
GPS Latitude: 32.47099444444444
GPS Longitude: -80.64906944444445
GPS Altitude: 21.23 meters
GPS Orientation: 1 degrees



Mar 19, 2026 at 1:48:04 PM
Beaufort SC 29907
United States
Lady's Island

Photo Taken: 03/19/2026 01:48:00 PM
GPS Latitude: 32.47099444444444
GPS Longitude: -80.64906944444445
GPS Altitude: 21.23 meters
GPS Orientation: 1 degrees



Mar 19, 2026 at 1:49:06 PM
Beaufort SC 29907
United States
Lady's Island

Photo Taken: 03/19/2026 01:49:00 PM
GPS Latitude: 32.471719444444446
GPS Longitude: -80.64937777777779
GPS Altitude: 20.8 meters
GPS Orientation: 1 degrees

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL



P1TJ-QJAP-426

Inspector: Colin Scherer

Start Date: 03/19/2026 Completed Date: 03/19/2026

Inspection Detail	
16. Working face as small as can efficiently and safely be managed	Yes
17. Asbestos containing material adequately handled	Not Applicable
<i>Comments:</i> No asbestos received recently	
18. Dead animals adequately handled	Not Applicable
19. All required equipment operational	Yes
<i>Comments:</i> One of the compactors was being worked on at time of inspection, but equipment present is sufficient.	
20. Access to fire equipment and fire fighting services	Yes
21. Disposal area graded to a minimum 1% slope	Yes
22. Adequate condition of ditches/swales	Yes

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL



P1TJ-QJAP-426

Inspector: Colin Scherer

Start Date: 03/19/2026 Completed Date: 03/19/2026

Inspection Detail

23. Adequate condition of berms/terraces/downchutes Yes

Comments:

Facility will be seeding bare slopes soon with warmer weather



Photo Taken: 03/19/2026 01:37:00 PM
 GPS Latitude: 32.469136111111111
 GPS Longitude: -80.6494888888889
 GPS Altitude: 4.25 meters
 GPS Orientation: 1 degrees



Photo Taken: 03/19/2026 01:41:00 PM
 GPS Latitude: 32.468394444444445
 GPS Longitude: -80.64741388888889
 GPS Altitude: 7.56 meters
 GPS Orientation: 1 degrees

24. Adequate condition of sedimentation ponds Yes

25. Control of Dust Yes

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL



P1TJ-QJAP-426

Inspector: Colin Scherer

Start Date: 03/19/2026 Completed Date: 03/19/2026

Inspection Detail

26. Control of Litter No

Comments:

Blown litter is significant in ditch along eastern edge.



Photo Taken: 03/19/2026 01:41:00 PM
 GPS Latitude: 32.4689305555556
 GPS Longitude: -80.64746111111111
 GPS Altitude: 6.96 meters
 GPS Orientation: 1 degrees

27. Control of Odors Yes

Comments:

Did not smell H2S odor along Middle Rd or at working face.

28. Control of Vectors Yes

29. Control of Fires/Open Burning Yes

30. Scales installed and functioning properly Yes

31. Scales calibrated adequately Yes

▶ **31a. Last date of calibration** 4/07/2025

32. Monitoring well pads are free of sediment buildup and standing water Yes

33. Monitoring wells pads are free of cracks Yes

34. Monitoring wells are labeled Yes

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL



P1TJ-QJAP-426

Inspector: Colin Scherer

Start Date: 03/19/2026 Completed Date: 03/19/2026

Inspection Detail

35. Monitoring wells are locked No

Comments:

Newest well (MW-4) does not have lock yet.



Photo Taken: 03/19/2026 01:32:00 PM
 GPS Latitude: 32.4726527777778
 GPS Longitude: -80.65114722222222
 GPS Altitude: 4.33 meters
 GPS Orientation: 6 degrees

36. Operating in accordance with approved plans Yes

37. Approved engineering drawings available Yes

38. Approved operational plan available Yes

39. Approved stabilization/landscaping plan available Yes

40. Approved contingency plan available Yes

41. Approved groundwater monitoring plan available Yes

42. Approved closure/post-closure plan available Yes

43. Required records maintained Yes

Corrective Action

1. Corrective Action Due Date 4/19/2026

Comments:

Get litter under control and lock for newest GW monitoring well.

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL



P1TJ-QJAP-426

Inspector: Colin Scherer

Start Date: 03/19/2026 Completed Date: 03/19/2026

Additional Comments

Record any additional information regarding the current activities at the site that has not already been captured in the previous questions

Work on getting litter under control and seeding bare areas. Operator states facility is getting quotes for gas management system (collection / flares); this could help manage H2S and odors. Current location of fill will be full in a few days, then operator states they are moving working face to peak of landfill and filling until final elevation is reached. Final cap will then be placed up top. Tarp is present for covering thinner truck turn-around area adjacent to working face.



Photo Taken: 03/19/2026 01:46:00 PM
 GPS Latitude: 32.47099722222222
 GPS Longitude: -80.64949722222222
 GPS Altitude: 12.78 meters
 GPS Orientation: 1 degrees

Signature

Name of those present during inspection	Maci Dean, Colin Scherer
1. Facility Representative	
1a. Facility Representative Name	Maci Dean
2. SCDES Inspector	
2a. SCDES Inspector Name	Colin T. Scherer

PRO DISPOSAL USA (BARNWELL RESOURCES)
CLASS 2 LANDFILL (P1TJ-QJAP-426)
Violation List

No Violations Found