

Table 4A. Analytical Results for Surface Water, First Quarter 2020

Plantation Pipe Line Company

Lewis Drive Remediation Site, Belton, South Carolina

Site ID #18693 "Kinder Morgan Belton Pipeline Release"

Location	Sample ID	Date Collected	Units	Analyte													
				Benzene	Ethylbenzene	Toluene	m&p-Xylene	o-Xylene	Naphthalene	MTBE							
Screening Value (µg/L):				2.2	a	530	a	1,000	a	NA	b	NA	b	NA	b	NA	b
SW-01	SW01-010820	1/8/2020	µg/L	1.49		1	U	1	U	2	U	1	U	5	U	1	U
	--	2/10/2020	--	NS-IW		NS-IW		NS-IW		NS-IW		NS-IW		NS-IW		NS-IW	
	SW01-031220	3/12/2020	µg/L	7.99		1	U	2.04		2	U	1.19		5	U	1.12	
SW-02	SW02-010820	1/8/2020	µg/L	7.25		1	U	1	U	2	U	1	U	5	U	1.89	
	SW02-021020	2/10/2020	µg/L	23.7		1	U	1.92		4.60		3.03		5	U	1.37	
	SW02-031220	3/12/2020	µg/L	7.71		1	U	1.30		2	U	1.38		5	U	2.32	
SW-03	SW03-010820	1/8/2020	µg/L	1	U	1	U	1	U	2	U	1	U	5	U	1	U
	SW03-021020	2/10/2020	µg/L	1	U	1	U	1	U	2	U	1	U	5	U	1	U
	SW03-031220	3/12/2020	µg/L	1	U	1	U	1	U	2	U	1	U	5	U	1	U
SW-04	SW04-010820	1/8/2020	µg/L	1	U	1	U	1	U	2	U	1	U	5	U	1	U
	SW04-021020	2/10/2020	µg/L	1	U	1	U	1	U	2	U	1	U	5	U	1	U
	SW04-031220	3/12/2020	µg/L	5.97		1	U	1.09		2	U	1.09		5	U	2.05	
SW-05	SW05-010820	1/8/2020	µg/L	1	U	1	U	1	U	2	U	1	U	5	U	1	U
	SW05-021020	2/10/2020	µg/L	1	U	1	U	1	U	2	U	1	U	5	U	1	U
	SW05-031220	3/12/2020	µg/L	1	U	1	U	1	U	2	U	1	U	5	U	1	U
SW-07	SW07-010820	1/8/2020	µg/L	1	U	1	U	1	U	2	U	1	U	5	U	1	U
	SW07-021020	2/10/2020	µg/L	1	U	1	U	1	U	2	U	1	U	5	U	1	U
	SW07-031220	3/12/2020	µg/L	1	U	1	U	1	U	2	U	1	U	5	U	1	U
SW-08	SW08-010820	1/8/2020	µg/L	1	U	1	U	1	U	2	U	1	U	5	U	1	U
	SW08-021020	2/10/2020	µg/L	3.05		1	U	1	U	2	U	1.19		5	U	1	U
	SW08-031220	3/12/2020	µg/L	1.07		1	U	1	U	2	U	1	U	5	U	1.50	
SW-09	SW09-010820	1/8/2020	µg/L	1	U	1	U	1	U	2	U	1	U	5	U	1	U
	SW09-021020	2/10/2020	--	NS-IW		NS-IW		NS-IW		NS-IW		NS-IW		NS-IW		NS-IW	
	SW09-031220	3/12/2020	µg/L	1	U	1	U	1	U	2	U	1	U	5	U	1.20	
SW-10	SW10-010820	1/8/2020	µg/L	1	U	1	U	1	U	2	U	1	U	5	U	1	U
	SW10-021020	2/10/2020	µg/L	1	U	1	U	1	U	2	U	1	U	5	U	1	U
	SW10-031220	3/12/2020	µg/L	1	U	1	U	1	U	2	U	1	U	5	U	1	U
SW-11	SW11-010820	1/8/2020	µg/L	1	U	1	U	1	U	2	U	1	U	5	U	1	U
	SW11-021020	2/10/2020	µg/L	1	U	1	U	1	U	2	U	1	U	5	U	1	U
	SW11-031220	3/12/2020	µg/L	1	U	1	U	1	U	2	U	1	U	5	U	1	U
SW-12	SW12-010820	1/8/2020	µg/L	1.36		1	U	1	U	2	U	1	U	5	U	1	U
	SW12-021020	2/10/2020	µg/L	18.9		1.54		2.68		20.7		5.13		5	U	2.39	
	SW12-031220	3/12/2020	µg/L	1	U	1	U	1	U	2	U	1	U	5	U	1	U
SW-13	SW13-010820	1/8/2020	µg/L	1	U	1	U	1	U	2	U	1	U	5	U	1.79	
	SW13-021020	2/10/2020	µg/L	4.44		1	U	1	U	2	U	1	U	5	U	1.50	
	SW13-031220	3/12/2020	µg/L	1	U	1	U	1	U	2	U	1	U	5	U	3.73	

Table 4A. Analytical Results for Surface Water, First Quarter 2020

Plantation Pipe Line Company

Lewis Drive Remediation Site, Belton, South Carolina

Site ID #18693 "Kinder Morgan Belton Pipeline Release"

Location	Sample ID	Date Collected	Units	Analyte													
				Benzene		Ethylbenzene		Toluene		m&p-Xylene		o-Xylene		Naphthalene		MTBE	
SW-14	SW14-010820	1/8/2020	µg/L	1	U	1	U	1	U	2	U	1	U	5	U	1	U
	SW14-021020	2/10/2020	µg/L	1	U	1	U	1	U	2	U	1	U	5	U	1	U
	SW14-031220	3/12/2020	µg/L	1	U	1	U	1	U	2	U	1	U	5	U	1	U

Notes:

^a South Carolina Department of Health and Environmental Control (SC DHEC) R.61-68, Water Classifications and Standards, Human Health for consumption of water and organism, June 27, 2014.

^b Screening levels for these analytes are not specified in SC DHEC R. 61-68.

^c The analyte was analyzed for, but was not detected above the laboratory reporting/quantitation limit. However, the laboratory reporting/quantitation limit is above the screening criteria.

The actual absence or presence of this analyte between the screening criteria and the laboratory reporting/quantitation limit can not be determined.

Samples analyzed by EPA Methods SW 8260B/8260D.

Bold indicates the analyte was detected above the method detection limit.

Gray shading indicates the analyte exceeded its screening value.

µg/L = microgram(s) per liter

FP = fishing pond

ID = identification

J = estimated

MTBE = methyl tertiary butyl ether

NA = not applicable

NS-DW = sample not collected due to location being in a different watershed

NS-HS = sample not collected due to health and safety concerns

NS-IW = sample not collected due to insufficient volume at surface water location

SW = surface water

U = analyte was not detected above the reported sample quantitation limit

DRAFT Data
DHEC Internal Use Only